

Schrader Quick Connects



ITEM#

- PM6101 - SCHRADER, O2, QUICK CONNECT X 1/8 NPT MALE
- PM6101S - SCHRADER, O2, QUICK CONNECT X 1/8 NPT MALE, SWIVEL
- PM6201 - SCHRADER, AIR, QUICK CONNECT X 1/8 NPT MALE
- PM6201S - SCHRADER, AIR, QUICK CONNECT X 1/8 NPT MALE SWIVEL
- PM6301 - SCHRADER, VACUUM, QUICK CONNECT X 1/8 NPT MALE
- PM6301S - SCHRADER, VACUUM, QUICK CONNECT X 1/8 NPT MALE, SWIVEL
- PM6401 - SCHRADER, N2O, QUICK CONNECT X 1/8 NPT MALE
- PM6401S - SCHRADER, N2O, QUICK CONNECT X 1/8 NPT MALE, SWIVEL



ITEM#

- PM6102 - SCHRADER, O2, QUICK CONNECT X 1/8 NPT FEMALE
- PM6102S - SCHRADER, O2, QUICK CONNECT X 1/8 NPT FEMALE, SWIVEL
- PM6202 - SCHRADER, AIR, QUICK CONNECT X 1/8 NPT FEMALE
- PM6202S - SCHRADER, AIR, QUICK CONNECT X 1/8 NPT, SWIVEL
- PM6302 - SCHRADER, VACUUM, QUICK CONNECT X 1/8 NPT FEMALE
- PM6302S - SCHRADER, VACUUM, QUICK CONNECT X 1/8 NPT FEMALE,SWIVEL
- PM6402 - SCHRADER, N2O, QUICK CONNECT X 1/8 NPT FEMALE
- PM6402S - SCHRADER, N2O, QUICK CONNECT X 1/8 NPT FEMALE, SWIVEL



ITEM#

- PM6103 - SCHRADER, O2, QUICK CONNECT X 1/4 NPT MALE
- PM6103S - SCHRADER, O2, QUICK CONNECT X 1/4 NPT MALE, SWIVEL
- PM6203 - SCHRADER, AIR, QUICK CONNECT X 1/4 NPT MALE
- PM6203S - SCHRADER, AIR, QUICK CONNECT X 1/4 NPT MALE, SWIVEL
- PM6303 - SCHRADER, VACUUM, QUICK CONNECT X 1/4 NPT MALE
- PM6303S - SCHRADER, VACUUM, QUICK CONNECT X 1/4 NPT MALE, SWIVEL

PM6403 - SCHRADER, N2O, QUICK CONNECT X 1/4 NPT MALE

PM6403S - SCHRADER, N2O, QUICK CONNECT X 1/4 NPT MALE, SWIVEL



ITEM#

PM6111 - SCHRADER, O2, QUICK CONNECT X HOSE BARB

PM6111S - SCHRADER, O2, QUICK CONNECT X HOSE BARB, SWIVEL

PM6211 - SCHRADER, AIR, QUICK CONNECT X HOSE BARB

PM6211S - SCHRADER, AIR, QUICK CONNECT X HOSE BARB, SWIVEL

PM6311 - SCHRADER, VACUUM, QUICK CONNECT X HOSE BARB

PM6311S - SCHRADER, VACUUM, QUICK CONNECT X HOSE BARB, SWIVEL

PM6411 - SCHRADER, N2O, QUICK CONNECT X HOSEBARB

PM6411S - SCHRADER, N2O, QUICK CONNECT X HOSEBARB, SWIVEL



ITEM#

PM6105 - SCHRADER, O2, QUICK CONNECT X DISS MALE

PM6105S - SCHRADER, O2, QUICK CONNECT X DISS MALE, SWIVEL

PM6205 - SCHRADER, AIR, QUICK CONNECT X DISS MALE

PM6205S - SCHRADER, AIR, QUICK CONNECT X DISS MALE, SWIVEL

PM6305 - SCHRADER, VACUUM, QUICK CONNECT X DISS MALE

PM6305S - SCHRADER, VACUUM, QUICK CONNECT X DISS MALE, SWIVEL

PM6405 - SCHRADER, N2O, QUICK CONNECT X DISS MALE

PM6405S - SCHRADER, N2O, QUICK CONNECT X DISS MALE, SWIVEL



ITEM#

PM6114 - SCHRADER, O2, QUICK CONNECT X DISS MALE W/CHECK

PM6114S - SCHRADER, O2, QUICK CONNECT X DISS MALE W/CHECK, SWIVEL

PM6214 - SCHRADER, AIR, QUICK CONNECT X DISS MALE, W/CHECK

PM6214S - SCHRADER, AIR, QUICK CONNECT X DISS MALE, W/CHECK, SWIVEL

PM6314 - SCHRADER, VACUUM, QUICK CONNECT X DISS MALE W/CHECK

PM6314S - SCHRADER, VACUUM, QUICK CONNECT X DISS MALE W/CHECK, SWIVEL

PM6414 - SCHRADER, N2O, QUICK CONNECT X DISS MALE W/CHECK

PM6414S - SCHRADER, N2O, QUICK CONNECT X DISS MALE W/CHECK, SWIVEL



ITEM#

PM6106 - SCHRADER, O2, QUICK CONNECT X DISS HEX NUT

PM6106S - SCHRADER, O2, QUICK CONNECT X DISS HEX NUT, SWIVEL

PM6206 - SCHRADER, AIR, QUICK CONNECT X DISS HEX NUT

PM6206S - SCHRADER, AIR, QUICK CONNECT X DISS HEX NUT, SWIVEL

PM6306 - SCHRADER, VACUUM, QUICK CONNECT X DISS HEX NUT

PM6306S - SCHRADER, VACUUM, QUICK CONNECT X DISS HEX NUT, SWIVEL

PM6406 - SCHRADER, N2O, QUICK CONNECT X DISS HEX NUT

PM6406S - SCHRADER, N2O, QUICK CONNECT X DISS HEX NUT, SWIVEL



ITEM#

PM6108 - SCHRADER, O2, QUICK CONNECT X DISS HANDTIGHT

PM6108S - SCHRADER, O2, QUICK CONNECT X DISS HANDTIGHT, SWIVEL

PM6208 - SCHRADER, AIR, QUICK CONNECT X DISS HANDTIGHT

PM6208S - SCHRADER, AIR, QUICK CONNECT X DISS HANDTIGHT, SWIVEL

PM6308 - SCHRADER, VACUUM, QUICK CONNECT X DISS HANDTIGHT

PM6308S - SCHRADER, VACUUM, QUICK CONNECT X DISS HANDTIGHT, SWIVEL

PM6408 - SCHRADER, N2O, QUICK CONNECT X DISS HANDTIGHT

PM6408S - SCHRADER, N2O, QUICK CONNECT X DISS HANDTIGHT, SWIVEL