

## Schrader Coupler



### ITEM#

PM6150 - SCHRADER, O2, COUPLER X 1/8 NPT FEMALE

PM6250 - SCHRADER, AIR, COUPLER X 1/8 NPT FEMALE

PM6350 - SCHRADER, VACUUM, COUPLER X 1/8 NPT FEMALE

PM6450 - SCHRADER, N2O, COUPLER X 1/8 NPT FEMALE



### ITEM#

PM6151 - SCHRADER, O2, COUPLER X 1/8 NPT MALE

PM6251 - SCHRADER, AIR, COUPLER X 1/8 NPT MALE

PM6351 - SCHRADER, VACUUM, COUPLER X 1/8 NPT MALE

PM6451 - SCHRADER, N2O, COUPLER X 1/8 NPT MALE



### ITEM#

PM6153 - SCHRADER, O2, COUPLER X 1/4 NPT MALE

PM6253 - SCHRADER, AIR, COUPLER X 1/4 NPT MALE

PM6353 - SCHRADER, VACUUM, COUPLER X 1/4 NPT MALE

PM6453 - SCHRADER, N2O, COUPLER X 1/4 NPT MALE



### ITEM#

PM6154 - SCHRADER, O2, COUPLER X HOSE BARB

PM6254 - SCHRADER, AIR, COUPLER X HOSE BARB

PM6354 - SCHRADER, VACUUM, COUPLER X HOSE BARB

PM6454 - SCHRADER, N2O, COUPLER X HOSE BARB



**ITEM#**

- PM6155 - SCHRADER, O2, COUPLER X DISS MALE
- PM6255 - SCHRADER, AIR, COUPLER X DISS MALE
- PM6355 - SCHRADER, VACUUM, COUPLER X DISS MALE
- PM6455 - SCHRADER, N2O, COUPLER X DISS MALE



**ITEM#**

- PM6156 - SCHRADER, O2, COUPLER X DISS HEXNUT
- PM6158 - SCHRADER, O2, COUPLER X DISS HANDTIGHT
- PM6256 - SCHRADER, AIR, COUPLER X DISS HEX NUT
- PM6258 - SCHRADER, AIR, COUPLER X DISS HANDTIGHT
- PM6356 - SCHRADER, VACUUM, COUPLER X DISS HEX NUT
- PM6358 - SCHRADER, VACUUM, COUPLER X DISS HANDTIGHT
- PM6456 - SCHRADER, N2O, COUPLER X DISS HEX NUT
- PM6458 - SCHRADER, N2O, COUPLER X DISS HANDTIGHT